

Grover Cleveland Golf Course



2012 - 2014 Capital Improvements:

Project Name	Problem/Issue	Type of Work Completed	Cost to Complete
Grover Cleveland Clubhouse	Age, leaking and rotted wood decking.	Replaced roof, vinyl siding, plumbing fixtures replaced and electric services upgraded.	\$28,437.00
Grover Cleveland Pro-Shop	Age, leaking and lots of rotted wood decking.	New roof. Wood decking, carpentry work. Electrical work and fascia/soffit/siding.	\$41,843.00
Grover Cleveland Maintenance	Age, leaking and some rotted wood decking.	New roof, siding and soffit, asbestos removal.	\$40,827.00



TOTAL: \$111,107.00