

District 4 BOM Update:

- **Pretreatment**

- **FOG Program**

Initial inspections at Food Service Establishments (FSE's) in the district are near complete. Follow-up letters and waiver applications (where necessary) were recently sent out.

Summary

4 FSE's not yet inspected (appointments to be made)
172 FSE's inspected

Of the 172 inspected FSE's:

- 51 FSE's have 750 gal (or larger) exterior Grease Interceptor
 - 44 were sufficiently cleaned
 - 7 were insufficiently cleaned
- 69 FSE's have interior grease traps
 - 28 were sufficiently cleaned
 - 41 were insufficiently cleaned
- 52 FSE's have no grease removal device